

555 PWM Controller Board

Connector K1 Pins Assignment:
1. Supply Input +10V ~ +50V DC
2. Supply Ground
3. Motor Positive (+) Terminal
4. Motor Negative (-) Terminal

